


1. Press the ON/OFF key to turn the scale on.
2. Wait for the display to show "0.00g"/ "0.0g" then press and hold the MODE key until the display shows "CAL", then release.
3. Press the MODE key again. The display will flash "CAL" followed by the required calibration weight.
4. Place the required calibration weight on the center of the platform. The display will show "PASS" then return to normal weighing mode. Calibration is complete!



GOVERNMENT  
EXHIBIT

18B